

January Tech Session

Bill Capps replacing the 3.54 with a 3.78

January 11 brought us our first tech session. Ten members gathered at Bill Capps home for changing of the gears in the rear end of his coupe. Dismantling the rear end went rather smoothly until we could not remove one gear. We made a side trip to Bob Beck's home for a special tool. It did the trick.

Assembly went well, everything looked good. Then a little noise detected when turning by hand. We disassembled again. It showed a worn race and two bearings. That was the end of the class.

This was a very informative session. A lot was learned.

Walt